



PW124B

Engine S/N 124367

Engine Details:

Time Since New	29,175
Cycles Since New	24,807
Time Since Overhaul	0.0
Cycles Since Overhaul	0

Latest Maintenance Info

Event	Date	Provider
Overhaul	July, 2007	Lufthansa AERO

Life Limited Components

Description	Part Number	Serial Number	TCSN	Cycle Life Limit	Cycles Remaining
LP Impeller	3038060	A00263P4	0	15,000	15,000
HP Impeller	3043293	A0026D60	0	15,000	15,000
Cover HPT Front	3039640	A0025R0A	0	15,000	15,000
Cover HPT Rear	3039639	A000XFA3	8,791	15,000	6,209
HTP Disk	3041511	A001736C	8,791	15,000	6,209
LPT Disk	3039512	A0016WYF	8,791	15,000	6,209
1st Stage PT Disk	3038513	A00277ND	0	30,000	30,000
2nd Stage PT Disk	3033914	A0026W3R	0	30,000	30,000
Air Seal Interstage	3039172	85B417	6,679	15,000	8,321
HPT Blades	3115601-01	VARIOUS	0	15,000	15,000

Accessories

Description	Part Number	Serial Number
E.E.C.U.	805813-1-005L5	91120617
M.F.C.U.	NOT INSTALLED	
A.F.U.	30048-0000-12	944
FUEL PUMP	NOT INSTALLED	
FUEL HEATER	NOT INSTALLED	
IGNITION EXCITER	9049400-1	NN95251255
IGNITION EXCITER	9049400-1	NA04057786
FLOW DIVIDER	3118512-01	1864
OVERSPEED GOVERNOR	8210-161C	1991139
OVERSPEED GOVERNOR PUMP	8210-286	2479752B
WIRING HARNESS	3116993-01	AA78972
OIL COOLER	3118263-01	WA4276
BLEED VALVE	NOT INSTALLED	
SERVOVALVE	NOT INSTALLED	